RG BUILDING SERVICES

DOMESTIC ELECTRICAL INSTALLATION CONDITION REPORT Requirements For Electrical Installations - BS 7671 IET Wiring Regulations

							Report Refe	rence:	L	.GC, 45	
1 / DETAILS OF THE PERSON ORDERING THE REPORT											
Client:	Brunel management										
Address:	Brunel Chambers, Devonshire Place, St Helier, Jersey, JE23RD										
2 REASON FOR PRODUCING THIS REPORT											
Reason for producing this report:											
Safety assessment requested by client.											
											_
Date(s) on which inspection and testing was carried out: 20/01/2020											
3 DETAILS OF THE INSTALLATION WHICH IS THE SUBJECT OF THIS REPORT											
Installation Address: No 45, La Grand Clos, St Helier, Jersey, JE2 3BB											
Evidence of additions/											
Estimated ag	e of wiring sy	/stem:	14	years		alterations:	additions/	No if y	es, estimated a	age:	years
Installation re	cords availab	ble? (Regul	ation 65	51.1)	N/A		Da	ate of last in	spection:	26/10/2	006
4 EXTENT AND LIMITATIONS OF INSPECTION AND TESTING											
Extent of the electrical installation covered by this report:											
100% of the installation.											
Agreed limitations including the reasons (see Regulation 653.2):											
Inspection where access is freely given. Limitation of inspection of cables installed behind ceilings and walls. No											
furniture is to be moved by engineers. Insulation resistance on circuits will only when we can guarantee no item on the circuit can be damaged. Bath panels are not to be removed for inspection.											
Agreed with:											
Operational limitations including the reasons:											
The inspection and testing detailed in this report and accompanying schedules have been carried out in accordance with BS 7671:2018 (IET Wiring Regulations) as amended to 2018.											
It should be noted that cables concealed within trunking and conduits, under floors, in roof spaces, and generally within the fabric of the											
building or underground, have not been inspected unless specifically agreed between the client and inspector prior to the inspection. An inspection should be made within an accessible roof space housing other electrical equipment.											
5 SUMMARY OF THE CONDITION OF THE INSTALLATION											
See page 3 for a summary of the general condition of the installation in terms of electrical safety.											
Overall assessment of the installation in terms of it's suitability for SATISFACTORY											
continued us	se*:					-					-
* An unsatisfactory assessment indicates that dangerous (Code C1) and/or potentially dangerous (Code C2) conditions have been identified.											
		ONS									
<u>RECOMMENDATIONS</u> Where the overall assessment of the suitability of the installation for continued use on page 1 is stated as 'UNSATISFACTORY', I/We											
recommend that any observations classified as 'Code 1 - Danger Present' or 'Code 2 - Potentially dangerous' are acted upon as a											
matter of urgency. Investigation without delay is recommended for observations identified as 'FI - Further Investigation Required'.											
Observations classified as 'Code 3 - Improvement recommended' should be given due consideration. Subject to the necessary remedial action being taken, I/we recommend that											
Subject to the the installatio					we rec	ommend that		5 Years	or change of	tenant/owr	ner
Note: The proposed date for the next inspection should take into consideration the frequency and quality of maintenance that the											
installation can reasonably be expected to receive during its intended life. The period should be agreed between relevant parties.											