



This report is not valid if the serial number has been defaced or altered

22431114

IPN18C

ELECTRICAL INSTALLATION CONDITION REPORT

Issued in accordance with BS 7671: 2018 - Requirements for Electrical Installations

PART 1 : DETAILS OF THE CONTRACTOR, CLIENT AND INSTALLATION		
DETAILS OF THE CONTRACTOR Registration No: 010706000 Branch No:	DETAILS OF THE CLIENT Contractor Reference Number (CRN): J159586 Name.Brunel Management Limited Address: Brunel Chambers, Devonshire Place, St. Heller, JERSEY Postcode: JE2 3RD Tel No: 01534750200	DETAILS OF THE INSTALLATION Occupier: N/A Address: 81 Belle Vue, La Route Des Quennevais, St. Brelade, JERSEY Postcode: JE3 8NL Tel No: N/A
Purpose for which this report is required: Clients request and to meet the Jersey landlords legislation Date(s) when inspection and testing was carried out: (08/01/2021) Records available: (
PART 3 : SUMMARY OF THE CONDITION OF THE INSTALLATION General condition of the installation (in terms of electrical safety): The general condition of the installation is good. The installation is wired in pvc pvc with RCBOs at the fuse board. The installation is fit for purpose		
Estimated age of electrical installation: (19 Overall assessment of the installation is: Satisfactory \$\ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \		
INSPECTION AND TESTING I, being the person responsible for the inspection and testing of the electrical installation, particulars of which are described in PART 7, having exercised reasonable skill and care when carrying out the inspection and testing of the existing installation, hereby CERTIFY that the information in this report, including the observations (page 2) and the attached schedules, provides an accurate assessment of the condition of the electrical installation taking into account the stated extent of the installation and the limitations on the inspection and testing. Name (capitals): Date: 08/01/2021		

@ Copyright Certsure LLP (July 2018)

^{*}An unsatisfactory assessment indicates that dangerous (CODE C1) and/or potentially dangerous (CODE C2) conditions have been identified in PART 6, or that Further Investigation (CODE FI) without delay is required.