

DOMESTIC ELECTRICAL INSTALLATION CONDITION REPORT

Issued in accordance with British Standard BS 7671 - Requirements for Electrical Installations

	BUILDING SERVICES						Certificate Reference:		CDR34		
1 DET	AILS OF THE CLIENT	2 ADDRI	ESS AND DE	TAILS OF T	HE INST	ALLATI	ON				
Client:	Brunel management	Installation:	lation: 34 Clos Du Ruisseau			E	Estimated age of electrical in		10 years		
Address:	Brunel Chambers Devonshire place St Helier Jersey	Address:	La Grand St Martin Jersey	Route De St	Martin	C [Evidence of alterations Notes	estimate	ed age: allation t number:	years N/A	
	Postcode: JE2 3	RD		Postcode:	JE3 6UU		Records of installation	Records held by:	N/A	١	
Purpose this report	for which is required: Safety assessment required:	•									
4 EXT	ENT OF THE INSTALLATION AND	LIMITATIONS OF T	HE INSPECT	ION AND TI	STING						
Extent of electrical in covered by report:	nstallation y this			Agreed and operational lir of the inspect testing (including reasons and pagreed with):	ion and le person	cables moved carried damage	tion where access is freely installed behind ceilings a by engineers. Insulation rout when we can guarant ed. Bath panels are not to	and walls. No esistance or ee no item or be removed	o furniture is n circuits will on circuit car d for inspect	to be only be be ion.	
should be unless specific by DEC I/We, be (see section 8) and the lim	ction and testing detailed in this report are noted that cables concealed within trunk ecifically agreed between the client and in LARATION ing the person(s) responsible for the inspon 3), having exercised reasonable skill a and the attached schedules (see section intations on the inspection and testing (see SPECTION, TESTING AND ASSESSM	ing and conduits, under aspector prior to the instance pection and testing of the and care when carrying and 16), provides an accur- accuracy accuracy.	r floors, in roof pection. An ins ne electrical instout the inspect	spaces, and g pection shoul tallation (as in tion and testin	enerally w d be made dicated by g, hereby o	vithin the to within are within the within are within the within the within are within are within are within the within t	fabric of the building or unden accessible roof space hous signatures below), particulars the information in this rep	rground, have ing other elect of which are ort, including	e not been ins ctrical equipm described on the observati	pected ent. page 1 ons (see	
Name:	Lewis McAteer	Position: C	Qualified Supe	ervisor	Signa	ature:		Da	ate: 20/1	2/2019	
Trading Address:		17 Beaulieu Park St Saviours Road				7 SUMMARY OF THE CONDITION OF THE INSTALLATION See page 3 for a summary of the general condition of the installation in terms of electrical safety. Overall assessment of the installation in terms of it's suitability for continued use*:					
Registration	on Number: 15420			ostcode: JE2 4RN			SATISFACTORY actory assessment indicates that dangerous (Code C1) and/or ngerous (Code C2) conditions have been identified.				
, logion and		. Ciopriorio i turriber.	one Number: 01534 780436								