



This report is not valid if the serial number has been defaced or altered

22166376

DPN18C

DOMESTIC ELECTRICAL INSTALLATION CONDITION REPORT Small installations up to 100 A single phase supply

Issued in accordance with BS 7671: 2018 – Requirements for Electrical Installations

PART 1 : DETAILS OF THE CONTRACTOR, CLIENT AND INSTALLATION		
DETAILS OF THE CONTRACTOR Registration No: 010706000 Branch No: 000 Trading Title: Smail & Richards Electrical Contractors Ltd Address: Top Floor C Store, Halcyon House, West Hill, St. Heller, Jersey Postcode: JE2 3HB Tel No: 01534723503	DETAILS OF THE CLIENT Contractor Reference Number (CRN): Name: Brunel Management Limited Address: Brunel Chambers, Devonshire Place, St. Helier, JERSEY Postcode: JE2 3RD Tel No: 750200	DETAILS OF THE INSTALLATION N/A Occupier: 8 WARREN COURT, Le Mont Felard, St. Lawrence, JERSEY Postcode: JE3 1NZ Tel No: N/A
PART 2 : PURPOSE OF THE REPORT	TO TO SECOND	
Purpose for which this report is required: Clients request and to meet the Jersey landlords legislation Date(s) when inspection and testing was carried out: (25/09/2020 - 28/09/2020) Records available: (X) Previous inspection report available: (X) Previous report date: (N/A)		
PART 3 : SUMMARY OF THE CONDITION OF THE INSTALLATION		
General condition of the installation (in terms of electrical safety): The general condition of the installation is good. The installation is wired in pvc pvc with RCBOs at the fuse board. The installation is fit for purpose Estimated age of electrical installation: (
PART 4: DECLARATION		
INSPECTION AND TESTING Liberal the person responsible for the inspection and testing of the electrical		asonable skill and care when carrying out the inspection and testing of the assessment of the condition of the electrical installation taking into account the Date: 28/09/2020

@ Copyright Certsure LLP (July 2018)

^{*}An unsatisfactory assessment indicates that dangerous (CODE C1) and/or potentially dangerous (CODE C2) conditions have been identified in PART 6, or that Further Investigation (CODE FI) without delay is required.