





This report is not valid if the serial number has been defaced or altered

20826958

IPN18C

	the state of the s	issued in accordance with BS 7671: 2018 – Requirements for Electrical Installations
PART 1 : DETAILS OF THE CONTRACTOR, CLIENT AND INSTALLATION		
Registration No: 010706000 Branch No: 000  Trading Title: Smail & Richards Electrical Contractors Ltd  Address: Top Floor C Store, Halcyon House, West Hill, St. Helier, Jersey	DETAILS OF THE CLIENT  Contractor Reference Number (CRN): J156585  Name: Brunel Management Limited  Address: Brunel Chambers, Devonshire Place, St. Helier, JERSEY  Postcode: JE2 3RD  Tel No: 01534750200	Address: 39 La Roseraie, Le Mont Pinel, St. Helier,
PART 2 : PURPOSE OF THE REPORT		
Purpose for which this report is required: Landlords report  Date(s) when inspection and testing was carried out: (17/12/2019 - 20/12/2019) Records available: ( × ) Previous inspection report available: ( N/A ) Previous report date: ( N/A )		
PART 3 : SUMMARY OF THE CONDITION OF THE INSTALLATION		
General condition of the installation (in terms of electrical safety):  The General condition of the installation is good  Estimated age of electrical installation: (19		
PART 4: DECLARATION		
INSPECTION AND TESTING  I, being the person responsible for the inspection and testing of the electrical installation, particulars of which are described in PART 7, having exercised reasonable skill and care when carrying out the inspection and testing of the existing installation, hereby CERTIFY that the information in this report, including the observations (page 2) and the attached schedules, provides an accurate assessment of the condition of the electrical installation taking into account the stated extent of the installation and the limitations on the inspection and testing.  Name (capitals):  Signature:  Date: 20/12/2019  Name (capitals):  Date: 20/12/2019  Date: 20/12/2019		

\*An unsatisfactory assessment indicates that dangerous (CODE C1) and/or potentially dangerous (CODE C2) conditions have been identified in PART 6, or that Further Investigation (CODE F1) without delay is required.