

Certificate Reference: CLC, 32


<b>1 DETAILS OF THE CLIENT</b> Client: Brunel Management Address: Brunel Chambers Devonshire Place St Helier, Jersey Postcode: JE2 3RD	<b>2 ADDRESS AND DETAILS OF THE INSTALLATION</b> Installation: Flat 32 Address: Clement Court Ann Street, St Helier Jersey Postcode: JE2 4AS	Estimated age of electrical installation: <span style="border: 1px solid black; padding: 2px;">10</span> years Evidence of alterations or additions: <span style="border: 1px solid black; padding: 2px;">No</span> if yes, estimated age: <span style="border: 1px solid black; padding: 2px;"> </span> years Date of previous inspection: <span style="border: 1px solid black; padding: 2px;">01/08/2019</span> Installation Cert number: <span style="border: 1px solid black; padding: 2px;">N/A</span> Records of installation available: <span style="border: 1px solid black; padding: 2px;">N/A</span> Records held by: <span style="border: 1px solid black; padding: 2px;">N/A</span>
---	---	---

**3 PURPOSE OF THE REPORT**  
 Purpose for which this report is required: Safety assessment requested by client.

<b>4 EXTENT OF THE INSTALLATION AND LIMITATIONS OF THE INSPECTION AND TESTING</b> Extent of the electrical installation covered by this report: <span style="border: 1px solid black; padding: 2px;">100% of the installation.</span>	Agreed and operational limitations of the inspection and testing (include reasons and person agreed with):	Inspection where access is freely given. Limitation of inspection of cables installed behind ceilings and walls. No furniture is to be moved by engineers. Insulation resistance on circuits will only be carried out when we can guarantee no item on circuit can be damaged. Bath panels are not to be removed for inspection.
--	--	--

The inspection and testing detailed in this report and accompanying schedules has been carried out in accordance with BS 7671:2008 (IET Wiring Regulations), as amended to 2015. It should be noted that cables concealed within trunking and conduits, under floors, in roof spaces, and generally within the fabric of the building or underground, have not been inspected unless specifically agreed between the client and inspector prior to the inspection. An inspection should be made within an accessible roof space housing other electrical equipment.

**5 DECLARATION**  
 I/We, being the person(s) responsible for the inspection and testing of the electrical installation (as indicated by my/our signatures below), particulars of which are described on page 1 (see section 3), having exercised reasonable skill and care when carrying out the inspection and testing, hereby declare that the information in this report, including the observations (see section 8) and the attached schedules (see section 16), provides an accurate assessment of the condition of the electrical installation taking into account the stated extent of the installation and the limitations on the inspection and testing (see section 4).  
**For the INSPECTION, TESTING AND ASSESSMENT of the report:**

Name: Lewis McAteer Position: Qualified Supervisor Signature:  Date: 01/11/2019

**6 DETAILS OF THE ELECTRICAL CONTRACTOR**  
 Trading Title: M.A.C. Energy  
 Address: 17 Beaulieu Park  
 St Saviours Road  
 St Helier, Jersey  
 Postcode: JE2 4RN  
 Registration Number: 15420 Telephone Number: 01534 780436

**7 SUMMARY OF THE CONDITION OF THE INSTALLATION**  
 See page 3 for a summary of the general condition of the installation in terms of electrical safety.  
**Overall assessment of the installation in terms of it's suitability for continued use\*:**  

**SATISFACTORY**

 \* An unsatisfactory assessment indicates that dangerous (Code C1) and/or potentially dangerous (Code C2) conditions have been identified.