ELECTRICAL INSTALLATION CONDITION REPORT

FT/EICR 3304000001700

for Residential or Similar Premises up to 100 A

Requirements for Electrical Installations BS 7671:2018+A2:2022 (IET Wiring Regulations 18th Edition)

etails of the Insta	llation		
Client	Brunel Management	Installation	Brunel Management
Address	Brunel Chambers Devonshire Place St. Helier Jersey	Address	Flat 14 St. Saviours Court St. Saviours Road St. Helier Jersey
Postcode	JE2 3RD	Postcode	JE2 3TL
eason for Produc	ing this Report This form is	to be used only for reporting on the con	dition of an existing installation.
5 year recommendation	on		
Date(s) on which the	inspection and testing were carried o	ut 03/07/2024 to 03/07/2	024
etails of Installati	on which is the Subject of th	nis Report	
Description of premise	es Residential or Similar 🗸 Cor	nmercial Industrial Other (ple	ase specify)
Estimated age of the	wiring system 25	years	
Evidence of alteration	s or addition Yes 🗸 N	o Not apparent if 'Yes', estin	mated 5 years
Records of installation	n available Yes 🗸 N	o Records held by	
Date of last inspection	Not Known E	lectrical Installation Certificate No. or previous	Inspection Report No.
xtent of Electrica	l Installation Covered by this	Report:	
Full test and inspection	on.		
Agreed Limitations	and Operational Limitations (Regu	ations 653 2)	
None	and Operational Elimitations (Negui	ations 033.2)	
110110			
Agreed with: N/A		Extent of Termination Sampling: 20%	
The inspection and to	esting detailed within this report and	accompanying schedule has been carried o	ut in accordance with BS 7671: 2018 (IET Wiring Regulations
amended to 2022			
			in the fabric of the building or underground have NOT been inspected nan accessible roof space housing other electrical equipment.
		· · · · · · · · · · · · · · · · · · ·	
	ondition of the Installation The installation (in terms of electrical	Overall assessment of the instal terms of its suitability for continu	
	installation is good throughout		
*An UNSATISFACTO	RY assessment indicates that dangero	ous (code C1), or potentially dangerous (code C	2) conditions have been identified
ecommendations			
			FORY I/we recommend that any observations classified as 'Danger elay is recommended for observations identified as 'Further Investigation's
	ervations classified as 'Improvement reco tallation is further inspected and tested by		ation. Subject to the necessary remedial action being taken, I/we
See Recommendatio	ns		
eclaration			
			signatures below), particulars of which are described above, having n this report, including the observations and the attached schedules,
· –		installation taking into account the stated extent and	·
Company	Excel Electrical Services Ltd.	Name: Jonathan Lloyd	and tested by Authorised for issue by Jonathan Lloyd
Address I	La Frette, La Rue de Causie, St. Cler		John Marien Lloyd
, add 635	La i rollo, La Mue de Odusie, St. Ciel		RD JRD
Postcode	JE2 6SQ		
Branch No.	ULC 00Q	Position:	
-	65827	Date: 03/07/2024	03/07/2024
			-11
chedule(s)	1 schedule(s) of inspection		
	The attached schedule(s) are	part of this document and this report is valid of	only when they are attached to it.